


DATE: August 8, 1990
TO: Division File
FROM: *CG* Chuck Gruntman, LPC, FOS, Maywood
SUBJECT: 0311020001 - Cook
Krohn Landfill
FOS

EPA Region 5 Records Ctr.



298141

On August 7, 1990 I stopped at the subject site to inspect the landfill and confirm that cover had been placed over the entire site. I met with Joe Pierro, the site manager, and Gary Deigan of Weston, Inc., from the site's engineering firm. They both accompanied me on the inspection.

The site had ceased accepting waste over a year ago and has certified that over 2 feet of final cover has been applied.

I walked the site. My inspection revealed that the entire site was covered. The depth of final cover could not be determined during this inspection, however, because the site operator refused to excavate test holes. It is the operator's contention that their engineer's certification of the depth is adequate for closure.

The majority of the site has an established vegetative cover. The remaining area has been newly seeded and has a vegetative growth of about two inches.

Three areas of erosion were identified during the inspection. These areas should be addressed before the erosion gullies cut completely thru the cover.

No violations were observed and the site appeared to be in compliance.

CG:lb:06251



CHESTNUT CLOSURE FACILITY
GROUNDWATER MONITORING WELL LOCATION




FIGURE 1 - LOCATIONS OF MONITORING WELLS